



# Glen Canyon

U.S. Department of the Interior  
Glen Canyon National Recreation Area



Estimated extent of veligers by year



Stars (★) indicate scattered individual adult mussels found in areas with no veligers detected. Mussels were likely scattered to these areas by boats. None of the scattered mussels found were within reproductive distance of each other. Photo: Gary Lahl

# Glen Canyon Dam

U.S. Department of the Interior  
Glen Canyon National Recreation Area



Fixed Wheel Gate



63 mussels in 2013



Thousands in 2014

Davis Dam Penstock Gate Oct.07



Lake Havasu

RECLAMATION

← Glen Canyon Dam may look like this in 2015